VISIBLE EMISSION NOTATIONS				
Inspector: R Long				
Date of Inspection:	5			
Shift: 1st Shift or 2nd Shift	Time:	9 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	NONE		
Visible Emission From Discharge Conveyor System	NOR	4		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R U	one			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	Time:	9 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>			Comments
Visible Emission From Shaker	Non		NONE	
Visible Emission From Discharge Conveyor System	NOR		V	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Lo	NG			
Date of Inspection:	115			
Shift: 1st Shift or 2nd Shift	ZL Time:	9AM		
Unit	Visual		Comments	
	Inspection			
	<u>NORMAL</u>			
	or			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	NOR		NONE	
Visible Emission From Discharge				
Conveyor System	NOR		<b>S</b>	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R long				
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	9AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR		NONE	
Visible Emission From Discharge Conveyor System	NOR		₹	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R love				
Date of Inspection: 11/5/15				
Shift: 1st Shift or 2nd Shift	Time:	9AN		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR		NONE	
Visible Emission From Discharge Conveyor System	NOR		\$	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R W	NO			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	Time:	9 AM		
Unit	Visual Inspection NORMAL			Comments
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR		NONG	
Visible Emission From Discharge Conveyor System	NOR		A	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS		
Inspector:	C1	-
Date of Inspection: 11/7/15	7	-
Shift: 1st Shift or 2nd Shift	Time: 9AM	-
Unit	Visual Inspection <u>NORMAL</u>	Comments

or ABNORMAL

NOR

NOR

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

• Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.

NONE

- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

Visible Emission From Shaker

Conveyor System

Visible Emission From Discharge

VISIBLE EMISSION NOTATIONS			_	
Inspector: R Long				
Date of Inspection: 11/8/15				
Shift: (1st Shift or 2nd Shift	Time:	9am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	2012		Nore	
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	
Inspector:	
1 long	
Date of Inspection:	
11/1/13	
Shift: 1st Shift or 2nd Shift	Time:
	91900

Constitution of the Consti		1 1 1 1 1		
Unit	Visual	-	Comments	
	Inspection			
	<u>NORMAL</u>			
	or			
	<u>ABNORMAL</u>			
Visible Emission From Shaker	NOR	N	IOPRE	
Visible Emission From Discharge	4.20	0	/	
Conveyor System	NOR		V	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

# VISIBLE EMISSION NOTATIONS

Inspector: R Low	· a			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shif	t Time:	9 Am		
Unit	Visual Inspection NORMAL		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR	NONE		
Visible Emission From Discharge Conveyor System	NOR	$\bigvee$		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Lanc	, 1			
Date of Inspection: 11/11/15	<del>j</del>			
Shift: (1st Shift) or 2nd Shift	Time:	9AM		
Unit	Visual Inspection NORMAL		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	Non	NON	$\mathcal{E}$	
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

AISIBLE FIMISSION MOTATIONS				
Inspector:	Long			
Date of Inspection:	5			
Shift: (1st )hift or 2nd Shift	Time: ¿	9 <sub>A</sub> M		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	NONA		
Visible Emission From Discharge Conveyor System	NOR	5.		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			
Inspector: R lo	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		
Date of Inspection: 11//3//	5-4		
Shift: 1st Shift or 2nd Shift	Time:	PAIL	
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments
Visible Emission From Shaker	NOV	MONE	
Visible Emission From Discharge Conveyor System	Non	4	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Low				
Date of Inspection:	5			
Shift: 1st Shift or 2nd Shift	Time:	9 AM		
Unit	Visual Inspection <u>NORMAL</u>			Comments
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOR		NONG	
Visible Emission From Discharge Conveyor System	NOR		5	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: R Low	G			
Date of Inspection:	115			
Shift: 1st Shift or 2nd Shift	Time:C	TRM		
Unit	Visual Inspection <u>NORMAL</u>		Comments	
	or <u>ABNORMAL</u>			
Visible Emission From Shaker	NOIL	Nd	VE	
Visible Emission From Discharge Conveyor System	Non		Tomasia.	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVIISSION NOTATIONS				
Inspector: R long	»			
Date of Inspection:	115			
Shift: 1st Shift or 2nd Shift	Time:	9 AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	Non	l.	
Visible Emission From Discharge Conveyor System	NOR		,	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

### VISIBLE EMISSION NOTATIONS

Inspector: R Lo	Nes			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	t Time:	9Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	NONE		
Visible Emission From Discharge Conveyor System	NOR	\$		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVIISSION NOTATIONS				
Inspector:	LOAM			
Date of Inspection:				
Shift: 1st Shift or 2nd Shift	Time:	9AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Will	Non	Į.	
Visible Emission From Discharge Conveyor System	NOR			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VICIDI E ENVICCIONI NIOTATIONIC

# VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: 1/18/15 Shift: 1st Shift or 2nd Shift Time: 9 Am

Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>	Comments
Visible Emission From Shaker	NOR	NONE
Visible Emission From Discharge Conveyor System	NOR	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

### VISIBLE EMISSION NOTATIONS

Inspector:	LONG			
Date of Inspection:	15			
Shift: 1st Shift or 2nd Shift	t Time:	9AM		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR	Non	I E	
Visible Emission From Discharge Conveyor System	NOR		,	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

# VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection:

Shift: / 1st Shift or 2nd Shift

Sinit. 1sc sinit or 2nd sinit	inne.	9 Am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	NOR		MON E	
Visible Emission From Discharge Conveyor System	Nor		S.	

Normal means emissions prevailing or expected to prevail 80% of time process in operation, not counting start up ro shut down

Time:

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS			_		
Inspector: Pupp	Moland				
Date of Inspection: 18415					
Shift: 1st Shift or 2nd Shift	Time: /	5. Ocam			
Unit.	Visual Inspection <u>NORMAL</u> or ABNORMAL			omments	
Visible Emission From Shaker	Norm				
Visible Emission From Discharge Conveyor System	Norm				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVIISSIUN NUTATIONS				
Inspector: Ruardo Plas	incic .			
Date of Inspection:	2010			
Shift: 1st Shift or 2nd Shift	Time:	Y:25pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Norm			
Visible Emission From Discharge Conveyor System	Noch			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS

# VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift or 2nd Shift Time:

<u></u>		C). C C C C V 70	:		
Unit	Visual	este de Maria de Maria de Maria (Cara).	da at la periodica Com	ments	
	Inspection		120 m		
	<u>NORMAL</u>	and the second s		en e	
	or			and the second second	epper and the second of the se
	<u>ABNORMAL</u>	127			
Visible Emission From Shaker	1				
	1 Carrier				
Visible Emission From Discharge					
Conveyor System	Nermal				

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

# VISIBLE EMISSION NOTATIONS

Inspector: Jime N GGR	100			
Date of Inspection: 11/45/15			•	
Shift: 1st Shift or 2nd Shif	t Time:	5.ph.		
Unit	Visual Inspection NORMAL or L ABNORMAL		Comments	
Visible Emission From Shaker	Normal	area and an area and a second a		
Visible Emission From Discharge Conveyor System	Normal	PROTOGRAMMES FAMILY		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector:	1 Thomas	L		
Date of Inspection:	/15	3 11		
Shift: 1st Shift or 2nd Shift	Time:	2:00 a.m.		
Unit	Visual		Comments	
Self-resident for the	Inspection			
	<u>NORMAL</u>			
An establish to the state of th	or			
	ABNORMAL			
Visible Emission From Shaker				
	Normal			
Visible Emission From Discharge				
Conveyor System	Monnoh			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: Jaime N Core	Cia			
Date of Inspection: //26/15		·		
Shift: 1st Shift or 2nd Shift	Time:	5pm		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Commen	
Visible Emission From Shaker	Normal	AND CONTRACTOR OF THE PARTY OF		
Visible Emission From Discharge Conveyor System	Moemal	,1000000000000000000000000000000000000		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS		
Inspector: Jamaa Th	ws My Wh	
Date of Inspection:		
Shift: 1st Shift or 2nd Shift	Time:	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>	Comments
Visible Emission From Shaker	N	
Visible Emission From Discharge Conveyor System	A /	

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS					
Inspector: Saine N Gal	Thy				
Date of Inspection: 11/17/15					
Shift: 1st Shift or 2nd Shift	Time:	5 ph			
	Visual Inspection NORMAL or ABNORMAL		Company of the compan	nments	
Visible Emission From Shaker	Normal	Conference and the conference of the conference			
Visible Emission From Discharge Conveyor System	Normal	<sup>New Control C</sup>			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

## VISIBLE EMISSION NOTATIONS

Inspector: 5 amail Thus	Was a se				
Date of Inspection: \\\\/\a\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\					
Shift: 1st Shift or 2nd Shif	t Time:	D 62			
Unit				Comments	Harmonia (Sept. Print Sept. Se
	Inspection NORMAL	Total Control of the		in the second of	
	or in the second		A CONTRACTOR OF THE CONTRACTOR		
	ABNORMAL			tik ili da saman da Saman da saman da sa Saman da saman da s	
Visible Emission From Shaker	1				
Visible Emission From Discharge	0				
Conveyor System					

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EIVIISSION NOTATIONS	/			
Inspector:	-ston			
Date of Inspection:	<i>'V</i>			
Shift: 1st Shift or 2nd Shift	t Time:	50m		
Unit	Visual Inspection <u>NORMAL</u> or ABNORMAL		Comments	
Visible Emission From Shaker	Nor			
Visible Emission From Discharge Conveyor System	No	Commence of the second		

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

## VISIBLE EMISSION NOTATIONS Inspector: Date of Inspection: Shift: 1st Shift (2nd Shift) Time: :000cm Unit Comments Visual Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker Visible Emission From Discharge Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

## **VISIBLE EMISSION NOTATIONS** Inspector: Date of Inspection: Shift: Time: 1st Shift 2nd Shift 5:00 Pm Unit Visual Comments Inspection NORMAL or **ABNORMAL** Visible Emission From Shaker Noin Visible Emission From Discharge Noon Conveyor System

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS	•	•		
Inspector: Pulour Nota	nd ju			
Date of Inspection:				
Shift: 1st Shift of 2nd Shift	Time:	5:00am		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments  The control of the control	
Visible Emission From Shaker	Normal			
Visible Emission From Discharge Conveyor System	Normal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission appearance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)

VISIBLE EMISSION NOTATIONS				
Inspector: DIME N CARCIO	9			
Date of Inspection: 1/30/15		,	•	
Shift: 1st Shift or 2nd Shif	t Time:	5D4.		
Unit	Visual Inspection <u>NORMAL</u> or <u>ABNORMAL</u>		Comments	
Visible Emission From Shaker	Noamed			
Visible Emission From Discharge Conveyor System	Noemal			

- Visible inspection must be performed during daylight operations and during the part of operations that would normally be expected to cause the greatest emissions. A trained employee shall recored whether emissions are normal or abnormal.
- Opacity is a measure of the degree to which emissions reduce the transmission of light and obscure the view of an object in the background.
- A trained employee is an employee who has worked at the plant at least one (1) month and has been trained in the appearance and characteristics of normal visible emissions for that specific process.
- If abnormal emissions are observed, the Permitte shall take resonable response steps to restore the operations and emissions to its normal or usual manner of operation and emission apperance. Failure to take steps or restore the operations is a diviation from the permit.
- Facility must record the response response steps taken to restore operations and visible emissions. (C.13)